



C8/R11: filter current anomalies due to the 22kHz modulation. Measuring may have been done before 22kHz filter but will so include the modulator current preventing us to detect motor disconnected.

Option 1: Active modulator as seen on many designs. Drawback is that it drives 60mA on line.

Option 2: Passive modulator. Maybe the best design. Drawback is the need for a dedicated transformer I haven't found the good one in stocks.

Diseqc	
24/03/2014 13:29:46	
Sheet: 1/1	